THT-CCM upgrade/ overhaul

To the latest state-of-the-art header and capper technology.

Your Benefits

- Extend the life cycle / span
- Boost overall machine performance
- Preserve the value of assets
- Ensure continued service support
- Option to produce oval tubes
- Increased product range
- Compatibility with EagleOwl™ remote service

Cost-effective upgrades mean lowrisk migration to more advanced and widespread technology to stay competitive. PackSys Global ensures continued service support and availability of service parts.

Our trained and qualified field engineers have performed overhauls on many PackSys Global machines, some of which have been in operation for over 30 years. We will live up to the trust you place in us.

You can recover the cost of your upgrade in less then six months while you continue to receive the benefits of new technology for years to come.

Electrical overhaul

Controls and electronics overhaul

A new operating panel, motors, drives and control system replaces the obsolete Siemens S5 with a contemporary B&R system. Software upgrades ensure that your older machine is brought in line with the prevailing technological standards.

- Gets rid of discontinued electronic components
- Simplifies handling
- Improves process stability

Extruder upgrade

Extruder revision consists of a new extruder screw and additional parts.

- Extends the life cycle
- Ensures continued availability of service parts

Mechanical overhaul

Complete mechanical overhauls will greatly boost the overall performance.
- Retains the asset value
- Ensures continued service support

Capper upgrade

Replace your CCM 4 with a CCM 8 and get rid of the UEB 2 accumulator. Maximizes maintenance intervals of mandrel cleaning cycles.
- Reduced space requirements
- Increased product range
- Push-on caps
Alternatively, a CCM 4 overhaul is also possible.

Top Seal

Secure your tubes with an aluminum membrane application. The additional Seal will make sure nothing can get in the finished tube and customers don't use the tube if the seal is broken before own use.

Top Seal